

Re-used crucks in Wharfedale and Airedale

(Copy for VAG Cruck Catalogue to be sent to:  
Dr. N. W. Alcock PSA, 18 Portland Place, Leamington Spa, Warwickshire, CV32 5EU)

- \*1. These blades may not be from the same truss  
\*2 Many blades re used as purlins are cut off at tie beam/spur level presumably to remove the elbow and make the timber more re-usable. The timber is also adzed to straighten it.

Location PARISH, NAMES	County (in former West Riding; put NY or WY for modern county)	Details as in existing Cruck Catalogue					Extra details		SOURCE (code for principal recorder's name; also number of record in Yorkshire Vernacular Buildings Group (NYV) files.)
		GRID REF.	STATE (R = reused; RD = reused, now demolished.)	USE of building in which cruck is reused. (A = agricultural; D = domestic)	NO of cruck trusses ( $\frac{1}{2}$ = one blade)	BLADE CURVE S = straight E = elbowed C = single curve D = double curve T = straight, curve at bottom	OTHER COMPONENTS of cruck truss reused: W = wall-plate; T = tie-beam with halvings; C = collar.	MODE OF REUSE e.g. to form purlins (= P); tie-beam (= T); lintel for barn wagon entry (= L) principal, rafter (= R)	
LANGBAR Beech Farm	NY	SE092513	(recently D by new building) RD	A	$\frac{1}{2}$	E	—	L	APA.
ADDINGHAM Low Cross Bank	WY	SE061503	R	A	$\frac{1}{2}$	C	W indicating a bay 3.51m long	L	NYV report no. ? MB
ADDINGHAM 16-18 Church Street	WY	SE082497	R	A+D	2+	T	—	P	NYV report forthcoming APA.
ADDINGHAM Shyall House	HOUSE WY	SE076477	R	D	0	—	T	P	APA
(see illustration)		BARN WY.	SE076477	R	A			stone gable wall	
SILSDEN Holden Gate	WY	SE067442	R	A	1	T	—	P	NYV report no. ? MB
SILSDEN Hole Farm	WY	SE028474	R	A	2 *1.	T? *2.	—	P	NYV report forthcoming AAB.
"	WY	SE028474	RD	A	1 *1.	T? *2.	—	P	AAB.

KEY TO SOURCES — APA = A Pacey MB = M. Birdsall AAB = Alison Armstrong Birdsall.

Re-used crucks in Wharfedale and Airedale

(Copy for VAG Cruck Catalogue to be sent to:  
Dr. N. W. Alcock FSA, 18 Portland Place, Leamington Spa, Warwickshire, CV32 5EU)

Location PARISH, NAMES	County (in former West Riding; put NY or WY for modern county)	Details as in existing Cruck Catalogue					Extra details			SOURCE (code for principal recorder's name; also number of record in Yorkshire Vernacular Buildings Group (NYV) files.)
		GRID REF.	STATE (R = reused; RD = reused, now demol ished.)	USE of building trusses in which cruck is reused. (A = agri- cultural; D = domestic)	NO of cruck trusses ( $\frac{1}{2}$ = one blade)	BLADE CURVE S = straight E = elbowed C = single curve D = double curve T = straight, curve at bottom	OTHER COMPONENTS of cruck truss reused: W = wall-plate; T = tie-beam with halvings; C = collar.	MODE OF REUSE e.g. to form purlins (= P); tie-beam (= T); lintel for barn wagon entry (= L) principal rafter. (= R)		
SILSDEN Hole Farm (contd)	WY	SE 028474	R	A	0	—	<sup>*3</sup> P (x2)	P	AAB	
"	"	"	RD	A	0	—	P (x2)	P	AAB	
"	"	"	R	A	$\frac{1}{2}$	T	—	Ornamental (in Ilkley)	APA	
SILSDEN Nicholsons Place	WY	SE 042464	R	D	$\frac{1}{2}$	T	—	T	NYV report forthcoming AAB	
SILSDEN Hutter Hill	WY	SE 024472	R	A	0	—	P	P	AAB	
"		"	"	R	A	0	—	P	L	AAB
LOTTERSDALE CROSS GREEN	NY	SD 963475	R	A	$\frac{1}{2}$	T	—	T	AAB	
"		"	"	R	A	$\frac{1}{2}$	T	—	L	AAB

\*3 purlins identified by wind brace halvings and pegs for rafters

Re-used crucks in Wharfedale and Airedale

(Copy for VAG Cruck Catalogue to be sent to:  
Dr. N. W. Alcock FSA, 18 Portland Place, Leamington Spa, Warwickshire, CV32 5EU)

Location PARISH, NAMES	County (in former West Riding; put NY or WY for modern county)	Details as in existing Cruck Catalogue					Extra details			
		GRID REF.	STATE (R = reused; RD = reused, now demol ished.)	USE of building in which cruck is reused. (A = agri- cultural; D = domestic)	NO of cruck trusses ( $\frac{1}{2}$ = one blade)	BLADE CURVE S = straight E = elbowed C = single curve D = double curve T = straight, curve at bottom	OTHER COMPONENTS of cruck truss reused: W = wall-plate; T = tie-beam with halvings; C = collar.	MODE OF REUSE e.g. to form purlins (= P); tis-beam (= T); lintel for barn wagon entry (= L) principal rafter. (= R)	SOURCE (code for principal recorder's name; also number of record in Yorkshire Vernacular Buildings Group (NYV files.)	
DRAUGHTON Matchless House	HOUSE NY	SE039523	R	D	$\frac{1}{2}$	NOT KNOWN (FRAGMENT)	—	SPINE BEAM (BEYOND SCARF JOINT)	NYV report AAB	
"	BARN NY	"	R	A	$\frac{1}{2}$	T	—	L	AAB	
"	BARN NY	"	R	A	0	—	P (x2) *3	P	AAB	
"	BARN NY	"	R	A	0	—	P (x2) *3	W	AAB	
SILSDEN Town Head Farm	WY	SE 046469	R	D	$\frac{1}{2}$	T	—	R	AAB	
HAWKSWORTH Intake Farm	WY	SE 147 428	R	A	$\frac{1}{2}$	E? *2	—	P	AAB	
"	WY	SE 147 428	R	A	0	—	P (x3)	P	AAB	
APPLETREWICK LOW HALL	BARN NY	SE 052602	R	A	1 $\frac{1}{2}$	T *2	—	T	AAB	

\*3 purlins identified by wood brace halves and pegs for rafters

Re-used crucks in Wharfedale and Airedale

(Copy for VAG Cruck Catalogue to be sent to:  
Dr. N. W. Alcock FSA, 18 Portland Place, Leamington Spa, Warwickshire, CV32 5EU)

Location PARISH, NAMES	County (in former West Riding; put NY or WY for modern county)	Details as in existing Cruck Catalogue					Extra details		SOURCE (code for principal recorder's name; also number of record in Yorkshire Vernacular Buildings Group (NYV) files.)
		GRID REF.	STATE (R = reused; RD = reused, now demol ished.)	USE of building in which cruck is reused. (A = agri- cultural; D = domestic)	NO of cruck trusses ( $\frac{1}{2}$ = one blade)	BLADE CURVE S = straight E = elbowed C = single curve D = double curve T = straight, curve at bottom	OTHER COMPONENTS of cruck truss reused: W = wall-plate; T = tie-beam with halvings; C = collar.	MODE OF REUSE e.g. to form purlins (= P); tie-beam (= T); lintel for barn wagon entry (= L) principal rafter (= R)	
APPLETREE WICK LOW HALL (LOW)	BARN NY	SE 052602	R	A	0	—	W	P	
BURNSALL MASON'S BARN	NY	SE 033612	R	A	1	T	—	T	NYV report forthcoming AAB
"		"	"	R	A	0	—	P(x2) <sup>#3</sup>	P
BAILDON BRACKEN HALL	BARN WY	SE 132391	RD	A	$\frac{1}{2}$ +	T	—	R	AAB
BEAMSLEY CURREN HALL BARN	NY	SD 092514	R	A	$\frac{1}{2}$ +	S? <sup>#2</sup>	—	R	AAB
"		"	SD 092514	R	A	0	—	P(x3)	P
ADDINGHAM Small Banks (Barn)	BARN WY	SE 078486	R	A	$\frac{1}{2}$	T	—	L	AAB
ADDINGHAM High Sanfit	HOUSE WY	SE 058507	R	D	$\frac{1}{2}$	T	—	Spine beam	AAB

#3 purlins identified by wind brace halvings and pegs for rafters

Re-used crucks in Wharfedale and Airedale

(Copy for VAG Cruck Catalogue to be sent to:  
Dr. N. W. Alcock FSA, 18 Portland Place, Leamington Spa, Warwickshire, CV32 5EU)

Location PARISH, NAMES	County (in former West Riding; put NY or WY for modern county)	Details as in existing Cruck Catalogue					Extra details			
		GRID REF.	STATE (R = reused; RD = reused, now demol ished.)	USE of building trusses in which cruck is reused. (A = agri- cultural; D = domestic)	NO of cruck trusses ( $\frac{1}{2}$ = one blade)	BLADE CURVE S = straight E = elbowed C = single curve D = double curve T = straight, curve at bottom	OTHER COMPONENTS of cruck truss reused: W = wall-plate; T = tie-beam with halvings; C = collar.	MODE OF REUSE e.g. to form purlins (= P); tie-beam (= T); lintel for barn wagon entry (= L) principal rafter. (= R)	SOURCE (code for principal recorder's name; also number of record in Yorkshire Vernacular Buildings Group (NYV) files.)	
ADDINGTONHAM Fell Edge	HOUSE WY	SE 073478	R	D	$\frac{1}{2}$	T	—	P	AAB	
"	HOUSE WY	SE 073478	R	D	0	—	P	P	AAB	
"	BARN WY	SE 073478	R	A	$\frac{1}{2}$	E?	—	P	AAB	
"	WY	SE 073478	R	A	0	—	P (x4)	P	AAB	
ADDINGTONHAM Ghyll House	BARN WY	SE 076477	R	A	$\frac{1}{2}$	?	—	L	NYV report for the wing AAB	
	WY	SE 076477	R	A	$\frac{1}{2}$	T	—	P	AAB	
	WY	SE 076477	R	A	—	—	P (x2) <sup>*3</sup> TWO WINDBRACE HALVINGS	P	AAB	
	WY	SE 076477	R	A	—	—	P (x2) <sup>*3</sup> ONE WINDBRACE HALVING	P	AAB	
ADDINGTONHAM Low Brocka Bank	BARN WY	SE	R	A	$\frac{1}{2}$	T	—	L	AAB	



