

087 N elevation with modern outshut

088 & 089 Plinth corner of N and E elevation

090 Doorway E elevation

091 E elevation

092 Ventilation hole? E elevation

093 Blocked doorway E elevation

094 Window with ?? lintels E elevation

095 S elevation

096 Plinth + large stone – earlier plinth? S elevation

097 S elevation junction with other building

098 Reused boskin stone above door S elevation

099/100/101 Doorway with chamfered jambs S elevation

102 Initials JHL on right jamb of door 99/100/101. 1.20m above base of doorway (JHL not a tall person...)
On opposite side – initial W: apotropaic. Virgin Mary symbol.

103 W elevation

104/105 Chamfers N end of W elevation

106/107 Chamfers and plinth c. middle of W elevation

108/109 Recessed doorway with complete set of chamfers W elevation

110 Blocked window? W elevation

111 Timber in outshut W elevation

Barn adjacent to above:

112 - 114 N elevation

115 Corner of N & W elevation, plus intruder

116 Blocked doorway W elevation

117 Plinth W elevation

118 - 121 S elevation, incl. plinth.















28 FD











