

Photos (See also additional AA notes at end of photos.)

7040013 South elevation central door – **stable**. Reused door jambs with notches.

014 Blocked doorway in N wall.

015 Window in N wall.

016 Blocked fireplace in NE corner – to keep the saddle dry; perhaps a granary above.

017 Corbel on E wall.

043 Finial on partition

044 Brickwork floor

018 S elevation **calf house** door

019 2 corbels N wall.

020 2 corbels S wall

021 calves

022 S elevation door to **stairway area**

023 Inside door – timbers over doorway

024 Ledge high on E wall – old roof line?

025 Window over door – more heavily angled on right than on left

027 Interior area

045 Old plinth on E wall – made of clearance boulders from local fields

028 S elevation door to **shippon**

029 Groop and step to booze – standing for cows

030 Boskins

031 Cranked boskin posts

032 First, narrower, boskin – holes in floor for uprights.

033 Reused timber over door.

034 Reused timber over window.

035 Groop

036 Main barn - hay mew over shippon.

037 IH initials over cart door

123 Initials IH on inside over door of E elevation cart door.

122 Mason's marks (LI = 51?) on inside of E elevation cart door.

038 Blocked forking holes (?) N wall

039 Reused timbers over west door

040 Earlier use of stonework in door jamb

041 Corbel next to second roof truss from N

042 S elevation cart door with two rooflines

### **AA's comments**

#### **East elevation**

Low vent holes because hay mew at ground level here.

2 post-1850 windows at lower level – only top and bottom lintels, no stone sides. Forking hole top left is pre-1850 – has stone sides.

#### **South elevation**

Padstones on plinth? For cruck timbers?

Door to stair area perhaps had passageway? Wall has been heightened. Quoins further up (to right of window).

Main cart door: early – mid C18. Cantilevered lintel – keystones came later.

Original roofline at door head height; another roofline above (Photo 042 above)

#### **Stable**

Probably always a stable. Floor is pre-1850 because not standard size bricks. May have come from Whinny Gill brickworks.

Fire place in corner to keep saddle dry. Perhaps granary above.

Partition has nice carved wood with finial. Perhaps had fancy columns.

May have originally been a winnowing door at the back of the stable, opposite the main cart door. c 1710?

Then the barn was heightened and this turned into a stable. Top window could be 1840.

Dating: 1730s, 1800, 1840/50 for top section. Several phases of building/change.

#### **North elevation**

Can see original roofline. Standard 3-bay barn. Phase 1 ended to left of window, at quoins. Then raised and raised again and joined to other building. (Sketch in field notes)

#### **West elevation**

Door in passage between 2 outshuts is C17. Chamfered/bevelled edges. Is perhaps missing door from house (Manor Cottage) which would have been larger?

Main wall – herring bone tooling = (18.

Earthwork in field is bank around demesne land of the Hall.

### **Staircase room**

Old plinth on E side – clearance boulders from local fields. (Photo 045)

Was yard outside dug out? Door was designed to be at ground level, not up step. 3 tie beams in flat above. Oak timber, local – knotty.

### **Shippon**

7 cows.

### **Main barn**

?Shippon? at N end – shippons always lime-washed. No other features of shippon.

Hay mew in centre.

Very odd arrangement. But floor now higher and concreted so difficult to work out.

Roof trusses: kingposts are bolted and so are mid C19. Also machine-sawn.

Very high and wide main door: why? Outside is C19.

Timber above door (with IH initials) is a reused timber floor joist.





















