

Notes for Burton House photos

22.11.13 LP, HN, AT, IT, LW, AA, WH

220072 Farmhouse and barn from east

- 073 Farmhouse S elevation
- 074 W elevation
- 075 Start of barn/W elevation
- 076 Slits in lower wall of barn W elevation
- 077 Slits in upper wall of barn W elevation
- 078 Current barn/former old house E elevation
- 079 Date stone RAJ? RAI? 163?5?
- 080 Date stone + adjacent door
- 081 E elev corner – window to cottage with staircase inside
- 082 Cottage door
- 083 Cottage window
- 084 Cottage S elevation
- 085 Cottage W elevation + 3rd house extension
- 086 + 08 Cottage interior
- 088 End of large plinth/join between house and 1st extension
- 089 + 90 House W elevation
- 091 – 5 W elevation
- 096 Interior – arched doorway in thick N wall of house body through to parlour
- 097- 9 Roof trusses
- 099 Blocked up ventilation slits/windows
- 100 – 1 N elevation of farmhouse
- 102 – 4 Cracked roof truss (E end of barn)
- 105 – 6 Baltic writing on cross-beam
- 107 A Holland 1943 etc graffiti
- 108 – 9 Farmhouse E elevation with earlier roof lines and extension