

290072 Rylstone House 1833/5 Expressed quoins (stick out)

073 View across the green looking towards Keepers Cottage etc

074 View to Rylstone Green farm late 18th. Cross-passage plan. Rebuild of 16th cent? Ventilator slits in barn. Various extensions. Mullioned windows. See also later photos.

075 Keepers Cottage. Acc. to owner was 1676 datestone on adjacent wall where taking-in door (?) had been below window. NW extension to Keepers is new. Old cottage plus adjacent were gardeners' cottages for Rylstone house (acc. to John Shuttleworth).

076 Barn Cottage and Keepers Cottage. Barn belonged to Rylstone Green farm (J Shuttleworth).

077 Barn Cottage SE elev.

078 Barn Cottage SW elev.

079 Barn Cottage NW elev.

080 Rylstone Green Farm N elev. Joins/extensions. Barn has 1800s quoins.

081 Rose Cottage. Extended to left.

082 Green Lane Cottage. (Barry Rawson may have plans for these. Bill to ask.)

083/4 Rylstone Green Farm – passage between farmhouse and barn

085 Orig. farmhouse S elev.

086 original timber door in passage.

087 Ventilation slit in barn N elev – stone with 2 grooves. (Anglo-Saxon????)

088-90 The Old Kennels WAW 1705

091 Beechwood. E elev. Acc to owner – was 17th cent barn which he converted in 1984. At back all was woodland. Why barn with no house? Would house have been in what is now a gap on E side?

092 Yew Tree Farm (wrong alignment on properties map) with datestone.

Grade 2 Listed (1954): House. Dated 1670, late C18-early C19 alterations. Gritstone rubble, graduated stone slate roof. 2 storeys, 2 bays. Quoins. C20 board door to far left, in a moulded quoined surround, the moulding carried over the triangular doorhead. A recessed plaque to lintel with evenly spaced raised letters, "1670 C B". Recessed chamfered mullion windows throughout, of 6 and 7 lights to ground floor, of 4 and 3 lights above. A central king mullion to the left window on each floor, and a continuous string course at first-floor level. Corniced ashlar stack to right. Interior not inspected at resurvey. The 1670 stack was probably opposite the entrance, this being altered when the house was reroofed. The carved detail and architectural elements of king mullions and string course are particularly fine for so small a house.

093 1670 CB datestone.

094 Taking in door on Yew Tree Barn (James Snowden rebuild)

095 Datestone over taking-in door CB? CR? 16..5? (1675??)

096 Lodge Cottage. House and barn with added stable to left. Windows have been raised by c.3 ft. Rylstone Lodge on right – new front extended out slightly, with expressed quoins.

Rylstone Lodge Grade II Listed (1969): House. Mid-late C18. Coursed squared gritstone rubble, graduated stone slate roof. 2 storeys, 3 bays. Rusticated quoins. Half-glazed C20 door to right in plain surround with cornice. Sashes with glazing bars in slightly projecting stone surrounds throughout. Corniced end stacks, square to right, with 4 flues. Interior: entrance hall with reset built-in cupboard with display shelves to left; rear stair-hall with a fine staircase of 3 straight flights, the ramped handrail supported by knopped column-on-vase balusters, the lowest being a single column. A rear corridor probably originally gave access to the service rooms, now Lodge Cottage, to left

097 Door in barn.

098/99 Stable – Georgian windows inserted into something older.